

FIG. 1




FIG. 2A




FIG. 2B




FIG. 3




FIG. 4




FIG. 5

612

604A

602

Motion Developer - Motion Developer 1

File Edit View Tools Help

Undo

Redo




Apply

Run

- Motion
- Reference Move
- Straight Line Move
- Arc Move
- Contouring Move

600

608



610

Configure | Move Constraints | Reference Parameters

Reference Move Block ...

Device:

PXI-7344 (1)

X Axis:

Axis 1

Units:

counts (steps)

Y axis:

Axis 2

Coordinate:

Vector Space 1

606

Block Setup

FIG. 6A

604B




FIG. 6B






FIG. 6C

604C




FIG. 6D




FIG. 6E

604D




FIG. 6F




FIG. 7




FIG. 8A




FIG. 8B




FIG. 8C



Beta 11








FIG. 8G




FIG. 9




FIG. 10




FIG. 11




FIG. 12



10051258 011802




FIG. 13

10051260-011803




FIG. 14

10051263 011802




FIG. 15

2025-12-10 10:50:00




FIG. 16